

Technical bulletin N 71 - 2018.02

New corner brackets for PVC hardware G-U for frames

from systems: E40, E45, E68 and E75

New corner brackets replace existing ones that are not any more in use

- **For E40/E45**

ET054717.00 replaces ET054700.00

- **For E68/E75**

ET054718.00 replaces ET991330.00




opening system with thermal break

E40

code/description	package/pcs	colour
ET 054717.00	70	MF

GU

extruded al. joint corner
bracket for GU
24.7 mm



attention
always use epoxy resin
for long lasting joining






opening system with thermal break

E45

code/description	package/pcs	colour
ET 054717.00	70	MF

GU

extruded al. joint corner
bracket for GU
24.7 mm



attention
always use epoxy resin
for long lasting joining






opening system with thermal break

E68

code/description	package/pcs	colour
ET 054718.00	80	MF

GU

extruded aluminium corner
bracket 18.9 mm
for GU



attention
always use epoxy resin
for long lasting joining





opening system with thermal break

E75


code/description	package/pcs	colour
ET 054718.00	80	MF

GU

extruded aluminium corner
bracket 18.9 mm
for GU



E75100



E75105

attention
always use epoxy resin
for long lasting joining

